

LATEST VEHICLE CONCERN FIXES



GTDi Camshaft Bearing Wear	14-17 MY Discovery Sport and RR Evoque
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">– The vehicle will not start.– The Check Engine Light is on, there is noise from the engine. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">– Wear is noted on the camshaft bearing surfaces. <p><u>Status:</u></p> <ul style="list-style-type: none">– There has been an increase in reports of this damage over the past weeks.– We are working to better understand all contributing factors to this damage.– Ensure proper maintenance has been carried out on any vehicle exhibiting this condition. Inspect the oil and oil filter for contamination to assist in determining correct level repair.– Raise an EPQR which includes pictures of the damage, a picture of an oil sample, and maintenance records for the vehicles.	  

