

LATEST VEHICLE CONCERN FIXES



Auxiliary Climate Control Not Cooling After Software Update

Range Rover, RR Sport 18MY

Customer Voice:

- A customer may report that the rear (auxiliary) climate control system is not cooling properly after vehicle has been serviced.

Technical Description:

- Vehicles with 4-zone climate control may stop producing cold air from the rear evaporator after a climate control module software update.
- This may be due to a software to hardware miss match that can prevent the auxiliary refrigerant control valve opening.

Status:

- Should this issue be encountered, please submit a TA case for the vehicle.
- A Webex may be required to load the correct software into the climate control module of the vehicle.
- SSM 74334 will be published for this concern.

