

TECHNICAL NEWS 195



Notice Information

Ref	10130
Posted Date:	
Posted To:	General Manager / Business Owner, Technician, Aftersales Manager, Service Leader / Advisor, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CAN) – March 8, 2019

TOL Ref. # 10130-SVC

Technical News 195

Technical News 195 is now available for download on the Triumph Technical News library located at **Triumph Online > Service/Technical > Technical News** or you can consult the attached **Technical News 195 PDF**. Please ensure your workshops and all relevant staff are aware of the contents and any absent staff are informed upon their return. Please also update your workshop service manuals, procedures and have a printed copy available where appropriate.

Contents		
Item	Subject	Model Affected
195.1	Replacement Chassis ECM Setup Process Tiger 1200 XR	Tiger 1200 XR
195.2	Replacement Chassis ECM Setup Process	Tiger 1200 XRX, Tiger 1200 XRX-LRH, Tiger 1200 XRT, Tiger 1200 XCX, Tiger 1200 XCA
195.3	Replacement Keyless ECM Setup Process	Speed Triple RS
195.4	Pin Point Test - ABS Modulator Communication	Tiger Sport
195.5	Pin Point Test - Power Source Voltage Drop/Voltage Rise	Tiger XR, Tiger XRT, Tiger XRX, Tiger XRX LRH, Tiger XC, Tiger XCA, Tiger XCX, Tiger XCX LRH
195.6	Intake Air Temperature Sensor Fixings	Tiger 1200 XR, Tiger 1200 XRX, Tiger 1200 XRX-LRH, Tiger 1200 XRT, Tiger 1200 XCX, Tiger 1200 XCA
195.7	Various Torque Changes	Speed Twin
195.8	Diagnostic Trouble Code C1151	Scrambler 1200 XC, Scrambler 1200 XE, Speed Triple RS, Tiger 1200 XRX, Tiger 1200 XRX-LRH, Tiger 1200 XRT, Tiger 1200 XCX, Tiger 1200 XCA

If you have any questions, contact your Regional Manager or call Triumph Customer Support at (888) 284-6288.