



SI B51 10 19  
Body Equipment

March 2019  
Technical Service

## LUGGAGE COMPARTMENT COVER SUPPORT STRAP MISSING

### MODEL

|                             |  |  |  |
|-----------------------------|--|--|--|
| G01 (X3)                    | G02 (X3)   |  |  |
| Produced 8/1/2018-8/27/2018 | With option code 493 Storage compartment package |  |  |

### SITUATION

The support strap used to secure the luggage compartment cover in the raised position may be missing.

### CAUSE


The incorrect luggage compartment cover may have been installed during production.

### CORRECTION

Inspect and replace the luggage compartment cover if necessary.

### PROCEDURE

1. Inspect the luggage compartment cover at location "2" shown below.



Is the support strap installed on the underside of the luggage compartment cover?

**Yes:** No further correction required, this bulletin does not apply.

**NO:** Proceed to step 2.

2. Install the correct luggage compartment cover outlined in the parts information section of this bulletin following repair instructions 51 47 102 "**Removing and installing/replacing the luggage compartment floor covering**".



Note: The part number outlined in the bulletin may be the same part number currently installed in the

vehicle. Any part ordered after this bulletin is published will include the updated parts with the correct support strap.

## PARTS INFORMATION

| Part Number     | Description                       | Quantity |
|-----------------|-----------------------------------|----------|
| <b>G01:</b>     |                                   |          |
| 51 47 9 462 948 | Floor carpet, luggage compartment | 1        |
| <b>G02:</b>     |                                   |          |
| 51 47 9 462 950 | Floor carpet, luggage compartment | 1        |

## WARRANTY INFORMATION

Covered under the terms of the BMW New Vehicle Limited Warranty for Passenger Cars and Light Trucks.

|                         |                         |  |
|-------------------------|-------------------------|--|
| <b>Defect Code:</b>     | <b>5147186500</b>       | <b>Hook/bracket, luggage compartment does not lock into position</b>             |
|                         |                         |  |
| <b>Labor Operation:</b> | <b>Labor Allowance:</b> | <b>Description:</b>  |
| 51 47 101               | Refer to AIR            | Removing and installing/replacing luggage compartment floor covering (Main Work) |
| Or:                     |                         |  |
| 51 47 601               | Refer to AIR            | Removing and installing/replacing luggage compartment floor covering (Plus Work) |

[ Copyright ©2019 BMW of North America, Inc. ]