




| | | |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------|----------------------------------------------|
|  | GROUP Electrical | MODEL 2018-2019MY Stinger (CK) |
| | NUMBER PS589 | DATE April 2019 |
|   | | |
| SUBJECT: KDS COOLING FAN ACTUATION TEST | | |

This Pitstop provides information regarding the KDS Cooling Fan Actuation Test which is only available for 2019MY~ Stinger (CK) vehicles.

A screenshot of the Cooling Fan Actuation Test for a 2018MY Stinger (CK) is shown below for reference with a result of “Operation Command Failed(0x22)” (or a possible result of “Operation Command Sent”) when the actuation was attempted. This is a normal operation of KDS as this actuation test is not supported for 2018MY Stinger (CK) and therefore does not require any further diagnosis or repair of the KDS or cooling fan circuit. If validation of proper operation of the cooling fan motor on a 2018MY Stinger (CK) is required, refer to the applicable ETM Manual on KGIS to manually and directly supply battery voltage and ground to the cooling fan motor.

