



# Technical Service Bulletin

SUBJECT:			No: <b>TSB-19-42A-006</b>
<b>CAUTION ADDED TO VALVE INSTALLATION OF TPMS TRANSMITTER - SMR</b>			DATE: <b>April 2019</b>
			MODEL: <b>2013-19 Outlander Sport/RVR</b>
<b>CIRCULATE TO:</b>	<input type="checkbox"/> GENERAL MANAGER	<input checked="" type="checkbox"/> PARTS MANAGER	<input type="checkbox"/> TECHNICIAN
<input checked="" type="checkbox"/> SERVICE ADVISOR	<input checked="" type="checkbox"/> SERVICE MANAGER	<input type="checkbox"/> WARRANTY PROCESSOR	<input type="checkbox"/> SALES MANAGER

## PURPOSE

This TSB updates the Body section of the affected Service Manual to add a Caution to the installation service points of the TPMS valve (rubber snap-in type only).

## AFFECTED VEHICLES

- 2013 - 2019 Outlander Sport/RVR with Rubber (snap-in) TPMS Valve

## AFFECTED SERVICE MANUALS

- 2013 - 2019 Outlander Sport/RVR Service Manual, Group 42-Body



Please make the indicated changes below to the 2013 - 2019 Outlander Sport/RVR Service Manual, in the following sections:

- Group 42-Body -> 42B-Keyless Operation System (KOS) -> TPMS Transmitter -> Removal and Installation -> Installation Service Points.
- Group 42-Body -> 42C-Wireless Control Module (WCM) -> TPMS Transmitter -> Removal and Installation -> Installation Service Points.

**NOTE: The change below (added Caution) applies ONLY to the rubber (snap-in) type of TPMS valve.**

## INSTALLATION SERVICE POINTS

### >>A<< VALVE INSTALLATION

#### **! CAUTION**

**Install the valve only onto the wheel first <Added>**

1. The projection shown by the arrow should face towards the outside of the wheel.

