

UBCO Service Bulletin

ID	UBC00007
DATE	27 March 2019
MODEL	2018 2x2
PRODUCTION	D0, D1, D2
GEOGRAPHY	All Markets (NZ, AU, USA)
TYPE	Notification
TITLE	Controller Remediation Update
RELATED NOTICE REMEDICATION	<p>Service Bulletin UBC00005</p> <p>The following Bulletin provides an update on the issue identified in the Service Bulletin UBC0005.</p> <p>UBCO have concluded analysis work on the root cause. This has resulted in specification changes to the existing controllers used with the manufacturer in the 2x2.</p> <p>Manufacturing of the revised controller design commenced in late 2018. Any controllers which do fail will be replaced with the revised design.</p> <p>All future production runs will utilise the revised controller design.</p> <p>If you have any concerns regarding this issue, please contact the UBCO Team at support@ubcobikes.com</p>