

SERVICE BULLETIN

Reference number:	SB-01-1263	Issued: 15 April, 2019
Subject:	Introduction of New Wiper Motor	
Model(s):	Vantage 19MY and DBS Superleggera	
VIN Range:	Vantage 19MY – up to N01632 DBS Superleggera – up to R00143	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Bulletin

The first Vantage 19MY and DBS Superleggera vehicles had a different windscreen wiper motor. This part is not available but can be replaced with the new part. A new wiper motor part cannot work together with the first wiper motor part. If one motor is replaced the other motor must also be replaced.

Workshop Procedure

This procedure is only necessary when you replace a windscreen wiper motor

CAUTIONS: THE WIPER SYSTEM WILL BE DAMAGED IF INCORRECT PARTS ARE USED.

1. Replace a wiper motor with the part number shown in Part Data.
2. Do a check of the part number for the other wiper motor.
3. If the other wiper motor part number is not the same, replace it with the part number shown in Part Data.

Part Data

Description	Part Number	Quantity
WIPER DD MOTOR ASSEMBLY RHS	KY63-17504-AB	1
WIPER DD MOTOR ASSEMBLY LHS	KY63-17503-AB	1

Warranty Data

Procedure and Labour Time

Description	Labour Time	ROT Code
Right Side Wiper Motor – Vantage 19MY – Remove and Install New Part	0.60 hours	01.16.BG
Right Side Wiper Motor – DBS Superleggera – Remove and Install New Part	0.75 hours	01.16.BG
Left Side Wiper Motor – Vantage 19MY – Remove and Install New Part	0.60 hours	01.16.BH
Left Side Wiper Motor – DBS Superleggera – Remove and Install New Part	0.65 hours	01.16.BH

If you have any questions related to this Service Bulletin, please contact: Aston Martin Technical Services
on: +44 (0) 1926 644720, email: askamtech@astonmartin.com,
Or contact your After Sales Manager.

The English version of this Service Bulletin is written in
Simplified Technical English to ASD-STE100™.