



# Service Bulletin

Bulletin No.: 17-NA-256

Date: May, 2019

## INFORMATION

**Subject:** Information on Trailer Brake Controller Blunt End Harness Breakout Connection

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Buick	Enclave	2018	2019				
Chevrolet	Traverse						

<b>Involved Region or Country</b>	North America, Russia, Middle East, Israel, Colombia, Chili, Peru and Africa
<b>Additional RPO's</b>	V92
<b>Condition</b>	The customer may not be able to find the location of the integrated wiring harness used for implementing a trailer brake controller to the vehicle.

Information



4847349

**Note:** This bulletin is to aid the customer in locating the trailer brake controller blunt end wires.

The trailer brake controller blunt ends (2) is part of the Instrument panel wiring harness and the blunt cut wires are located under the left instrument panel, behind the front side door sill garnish molding trim.

If the customer wishes to have an aftermarket brake controller installed in their vehicle, it would be considered as a Customer Pay option.

**Parts Information**

No parts are required for this repair.

<b>Version</b>	2
<b>Modified</b>	Released August 9, 2017. Revised April 30, 2019 - Added 2019 Model Year.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY  
TECHNICIAN  
CERTIFICATION