

Subject: Engineering Information – Service Engine Soon (SES) Light On, Rough Idle, Running Lean, Engine Air Leak From the Foul PCV Tube and/or Whistle Type Noise, DTCs P0171 and/or P0174 Set

This PI has been revised to end the need for information from the field. Please discard PIE0501.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Silverado 1500 (New Model)	2019	2019			Equipped with 5.3L or 6.2L Engine (RPOs L84, L87)	All
GMC	Sierra 1500 (New Model)						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released February 01, 2019 Revised April 23, 2019 – Ended the need for further information from the field.