



SI B12 11 19
Engine Electrical Systems

April 2019
Technical Service

ERRONEOUS ELECTRIC FAN VOLTAGE FAULT STORED IN THE DME

MODEL

G05 (X5 Sports Activity Vehicle)	G07 (X7 SAV)	G20 (3 Series Sedan)	G29 (Z4 Roadster)
----------------------------------	--------------	----------------------	-------------------

Equipped with the B46, B58, or N63 produced thru June 20, 2019

SITUATION

The following faults are erroneously store in the Digital Motor Electronics (DME).

Fault code:	Control module:	Fault code text:
1A2014	DME	Electric fan, function: Switch-off due to undervoltage

There is no customer-facing symptom nor related check control message displayed.

CAUSE

A software error may cause this erroneous fault to be stored in the DME.

CORRECTION

Erroneous fault **1A2014** can be ignored; it will be removed as of ISTA 4.17.1x (estimate availability late June, 2019)

PROCEDURE

If the following fault is stored: **1A2014**:

- Ignore the fault and clear fault memory **after all other** diagnostics have been completed.

WARRANTY INFORMATION

This service information bulletin provides technical, diagnostic and/or repair-related information.

[Copyright ©2019 BMW of North America, Inc.]