



# Service Bulletin


Bulletin No.: 19-NA-083

Date: April, 2019

## TECHNICAL

**Subject:** Creaking Type Noise Around Front Strut Mounts When Steering Wheel is Turned Right or Left in Colder Weather

Brand:	Model:	Model Year:		Breakpoint:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Impala	2014	2019				

<b>Involved Region or Country</b>	North America and N.A. Export Regions
<b>Condition</b>	Some customers may comment on a creaking type noise heard from the front strut mounts when the steering wheel is turned right or left in colder weather.
<b>Cause</b>	 <p style="text-align: right;">5315933</p> <p>This condition may be caused by a gap between the bearing lower housing and top mount body.</p>
<b>Correction</b>	Replace both front strut mounts. Refer to <i>Strut, Strut Component, or Spring Replacement</i> in SI.

## Parts Information

Causal Part	Description	Part Number	Qty
X	MOUNT, FRT SUSP STRUT	84583352	2

## Warranty Information

For vehicles repaired under warranty, use:

Labor Operation	Description	Labor Time
8033791	Strut, Strut Component, or Spring Replacement - Both Sides	Use Published Labor Operation Time

Version	1
Modified	Released April 17, 2019

