



Service Bulletin

Bulletin No.: 19-NA-086

Date: April, 2019

INFORMATION

Subject: Rear Tail Lamp Turn Signal Intermittently/Temporarily Flashes Quickly at Low Temperatures

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Malibu	2016	2019			All	All

Involved Region or Country	North America and N.A. Export Regions
Condition	Some customers may comment that the rear lamp outage detection signal may activate a quick flash for a short amount of time if the vehicle is exposed to temperatures colder than -15°C (5°F). This quick flashing will go back to normal after about 25 seconds.
Cause	The cause of the condition may be that if the vehicle is exposed to temperatures colder than -15°C (5°F), the rear lamp outage detection signal may activate a quick flash for a short amount of time. This quick flashing will go back to normal after about 25 seconds.
Correction	Please communicate to the customer that the tail lamp functionality is operating as intended, and this is a normal condition of their vehicle. Please share this information with the customer, including a copy of this bulletin.

Version	1
Modified	Released April 17, 2019

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT VOLUNTARY
TECHNICIAN
CERTIFICATION