

## LATEST VEHICLE CONCERN FIXES



Vehicle Heavier Than Expected	Range Rover / Range Rover Sport 2016 MY Onwards
<p><b><u>Customer Voice:</u></b></p> <ul style="list-style-type: none"><li>- Vehicle steering feel heavier than expected</li></ul> <p><b><u>Technical Description:</u></b></p> <ul style="list-style-type: none"><li>- This may be caused by the Bulkhead Seal Assembly binding with the steering column upper shaft</li><li>- No warning lamps displayed on the Instrument Cluster or DTC stored</li></ul> <p><b><u>Status:</u></b></p> <ul style="list-style-type: none"><li>- LTB01224 To be published when the new steering shaft (LR134726) is available, ETA for part is the 5<sup>th</sup> of May</li></ul>	

