

# LATEST VEHICLE CONCERN FIXES



## Auxiliary Climate Control Not Cooling After Software Update

Range Rover, RR Sport 19MY

### Customer Voice:

- A customer may report that the rear (auxiliary) climate control system is not cooling properly after vehicle has been serviced.

### Technical Description:

- A limited number of vehicles with 4-zone climate control may not produce cold air from the rear evaporator due to a climate control module software error.

### Status:

- Revised HVAC software has been created to address this concern.
- Service Action N320 will be published to proactively update HVAC module software for vehicles affected with this concern.

