

## Liftgate closes independently after reconnecting battery

---

|                   |                                                  |
|-------------------|--------------------------------------------------|
| Topic number      | LI88.50-P-069630                                 |
| Version           | 1                                                |
| Function group    | 88.50 Trunk lid                                  |
| Date              | 04-04-2019                                       |
| Validity          | GT X290 produced January 19 2018 to April 1 2019 |
| Reason for change |                                                  |
| Reason for block  |                                                  |

---

### Complaint:

If the battery is disconnected for an extended period of time while the liftgate is open, the liftgate may close when the battery is re-connected.

### Cause:

Possible communication fault in control units. No fault codes are present.

### Remedy:

SCN code the Tailgate Control Unit (N121/1)

|                                                |
|------------------------------------------------|
| Symptoms                                       |
| Body / Door/Flap / Power closing / Malfunction |

| Control unit/fault code                   |            |            |
|-------------------------------------------|------------|------------|
| Control unit                              | Fault code | Fault text |
| N121/1 - Tailgate control (HKS) (PTCM290) | -          | -          |