

## **Preliminary Information**

## PIT5675 Diagnostic Tip: Loss of Power Steering Assist May Have Chassis Bus Communication Codes or C0800 in The PSCM

## <u>Models</u>

Brand:	Model:	Model Years:	VIN:		Engine	Transmissions:
			from	to	Engine:	Transmissions.
Chevrolet	Equinox	2018 - 2019	All	All	All	All
GMC	Terrain	2018 - 2019	All	All	All	All

Condition:Loss Of Power Steering Assist May Have Chassis Bus Communication Codes Or C0800 In The PSCM.Cause:Inspect G112 for incorrect nut installed not providing proper clamp load on the ground lug.	Involved Region or Country:	North America
	Condition:	
	Cause:	Inspect G112 for incorrect nut installed not providing proper clamp load on the ground lug.

Engineering is reviewing this concern with the assembly plant . This may become a bulletin as more information becomes available.

## Version History

Version	1		
Created	04/18/2019 - Created on		



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.