



Preliminary Information

PIT5632A Squeak, Rattle or Tick Noise from B-Pillar Area

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Colorado	2018 - 2019	All	All	All	All
GMC	Canyon	2018 - 2019	All	All	All	All

Involved Region or Country:	North America
Additional RPO/s:	None
Condition:	Squeak , tick or rattle noise from the B-Pillar area.
Cause:	Metal to metal contact of the inner and outer panels.

Correction:

Engineering is investigating this concern. The root cause has been determined and best path to repair is being evaluated. Attempt no repair at this time. DO NOT put expanding foam in the pillar this will not repair the concern and will make the eventual repair more difficult. This PI will be updated when the repair procedure has been established.

Version History

Version	2
Modified	09/19/2018 - Created on. 04/29/2019 - Updated Model Years.



GENERAL MOTORS