



# Preliminary Information

## PIT5675A Diagnostic Tip: Loss of Power Steering Assist May Have Chassis Bus Communication Codes or C0800 in The PSCM

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Equinox	2018 - 2019	All	All	All	All
GMC	Terrain	2018 - 2019	All	All	All	All

<b>Involved Region or Country:</b>	<b>North America</b>
<b>Condition:</b>	<b>Loss Of Power Steering Assist May Have Chassis Bus Communication Codes Or C0800 In The PSCM.</b>
<b>Cause:</b>	<b>Inspect G112 for a standard nut versus a shouldered nut similar to the one shown below. If the standard nut is installed it will not provide proper clamp load on the ground lug.</b>



Engineering is reviewing this concern with the assembly plant. This may become a bulletin as more information becomes available.

### Version History

<b>Version</b>	<b>2</b>
<b>Created</b>	<b>04/18/2019 - Created on. 04/30/2019 - Updated to add picture.</b>

