

Original Publication Date: March 28, 2019

To: All Toyota Dealer Principals, General Managers, Service Managers, and Parts Managers

**SPECIAL SERVICE CAMPAIGN K0B (*Remedy Notice*)**

**Certain 2018 – 2019 Model Year Tacoma and Tundra  
Millimeter Wave Radar Sensor**

Model / Years	Production Period	Approximate Total Vehicles
2018 – 2019 Tacoma	Late June 2017 – Mid-December 2018	280,200
2018 – 2019 Tundra	Early August 2017 – Mid-December 2018	160,600

Specific information for Region support is provided below.

**Condition**

The involved vehicles are equipped with a Pre-Collision System (PCS) that may automatically apply the brakes if the system detects a potential collision. Due to the mounting of one of the system's sensors, it is possible for water to enter the sensor. This can lead to PCS deactivation or inadvertent brake activation resulting in limited deceleration for a short duration of time.

Please refer to the Owner's Manual for additional information regarding the PCS system operation.

**Dealer Notification**

The attached dealer letter will be sent to all Toyota dealers on March 28, 2019.

*Please reference the attached Dealer Letter for additional details.*

Please review this notification with your staff to assure that all relevant personnel have been briefed regarding this subject.

Thank you for your cooperation.