

Daimler Trucks

North America LLC Customer Advisory Letter

Subject : Rear PTO Pump Support

Trucks Affected: (See last Page)

Date; 2-25-19

Subject; Rear Transmission Support Bracket


Issue; PTO Support

Those Fuller transmissions with the PTO rear mounted with a HYD Pump mounted to the PTO. There were some mounted with a support strap attaching to a single 3/8 bolt at the top of the transmission to one of the pump studs. We now have a support bracket that can be ordered from the location below that will bolt to the 2 - 5/8" studs from the top of the transmission and to the rear of the pump. The pump should have 2 studs, if they are now installed on the top of the pump, remount where the bracket will attach.

The pump support brackets costs 200.00 per truck, you will need to set up billing.

Blalock Machine Works Inc
2201 N Monroe St
Albany, GA 31701

Tele (229) 432-5161





Submit your repair claim to Ryder Warranty if the repair is made at Ryder, if the repair is made at a dealer, please have the dealer contact Glenn Thornton 919-618-1737.

Ryder #	UR #	Vin	Model	VEHICLE TYPE (TYPE OF UP-FITTING)	Address	City
809057	10866753	3AKJHLFG0KSKH4764	New Cascadia	STD 186 WB Tractor/ new spec	840 S Maple	Montebello CA
809058	10841091	3AKJHLFG2KSKH4765	New Cascadia	STD 210 Tractor - EATON ULTRASHIFT	404 H IRL LN	Fruitland MD
834423	10882415	3AKJHLFG1KSKP3434	New Cascadia	STD 186 WB Tractor/ new spec	2400 Industrial Dr	Madison WI
867300	12997692	3AKJHLFG1KSKX9492	New Cascadia	MTN 186 WB Tractor/new spec	201 Forsyth Dr	Charlotte NC