



No.: 14 TS-5Rev
Mar 12, 2019

TO: Service Locations

FROM: Service Systems Development

SUBJECT: **Replacing Damaged Aftertreatment Sensor Bosses**

ISSUE

This letter has been removed as the information is now available on TechLit.

CONTACT INFORMATION

Please contact the Detroit™ Customer Support Center at 800-445-1980 or email csc@daimler.com if you have any questions.