

SSM 48001 - 2013-2019 Explorer - 2.3L EcoBoost - Accessory Drive Belt Noise And/Or Charging System Warning Indicator Illuminated

Some 2016-2019 Explorer vehicles equipped with a 2.3L EcoBoost engine may exhibit a squeal noise from the accessory drive belt, illuminated charging system indicator, and/or damaged alternator pulley. Accessory drive belt DA8Z-8620-G has been released to eliminate this noise and alternator pulley damage. Refer to Workshop Manual (WSM), Section 303-05 for the removal and installation procedure. For claiming, use causal part 8620 and applicable labor operations in Section 06 of the Service Labor Time Standards (SLTS) Manual.