



Preliminary Information

PIC6074A New Updated Calibrations Now For DTC P0AA6 To Prevent Possible Repeat Occurrences

Proactive

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Volt	2012	All	All	All	All

Supersession Statement

This PI was superseded to update Recommendation/Instructions. Please discard PIC6074.

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Condition / Concern

Some 2012 Volts with prior TAC Case and Calibration updates prior to September 5, 2014 for DTC P0AA6 did not receive the BECM (K16) calibration update.

Recommendations / Instructions

Certain 2012 Volts that were serviced at the dealer and did not get the latest BECM (K16) software.

Please see the list on VINs to confirm if the vehicle will need the software update per latest version of [PIC5920](#).

It is recommended that dealers reach out to these customers on the VIN list who have prior TAC cases for P0AA6 and install the latest BECM (K16) calibrations.

If your vehicle is not on the list, follow normal SI diagnosis.

1G1RA6E49CU104611	1G1RB6E44CU101354	1G1RD6E42CU100827	1G1RD6E47CU109863
1G1RB6E40CU100718	1G1RB6E44CU106165	1G1RD6E42CU102092	1G1RD6E48CU101349
1G1RD6E43CU101078	1G1RB6E45CU100343	1G1RD6E43CU100691	1G1RD6E48CU101965
1G1RA6E43CU104376	1G1RB6E45CU101606	1G1RD6E43CU100951	1G1RD6E48CU102484
1G1RA6E44CU100823	1G1RB6E45CU104327	1G1RD6E43CU101193	1G1RD6E48CU105739
1G1RA6E45CU101284	1G1RB6E46CU102148	1G1RD6E43CU103008	1G1RD6E49CU101571
1G1RA6E45CU104105	1G1RB6E46CU102344	1G1RD6E43CU105986	1G1RD6E49CU101893

1G1RA6E45CU104380	1G1RB6E48CU101549	1G1RD6E44CU100425	1G1RD6E49CU101893
1G1RA6E48CU102719	1G1RB6E48CU102524	1G1RD6E44CU101204	1G1RD6E49CU102073
1G1RA6E49CU101028	1G1RB6E48CU103592	1G1RD6E44CU101607	1G1RD6E49CU104115
1G1RB6E40CU100878	1g1rb6e49cu102516	1G1RD6E44CU101932	1G1RD6E49CU104115
1G1RB6E40CU101822	1G1RB6E4XCU101357	1G1RD6E44CU105091	1G1RD6E49CU105958
1G1RB6E40CU101920	1G1RB6E4XCU101729	1G1RD6E45CU101289	1G1RD6E4XCU100588
1G1RB6E40CU102534	1G1RB6E4XCU102458	1G1RD6E45CU101468	1G1RD6E4XCU101384
1G1RB6E41CU106267	1G1RB6E4XCU102511	1G1RD6E45CU103446	1G1RD6E4XCU101854
1G1RB6E42CU100395	1G1RC6E45CU102204	1G1RD6E46CU101026	1G1RD6E4XCU102003
1G1RB6E42CU101630	1G1RD6E40CU100793	1G1RD6E46CU101138	1G1RD6E4XCU102101
1G1RB6E42CU107654	1G1RD6E40CU101264	1G1RD6E46CU101768	1G1RD6E4XCU102616
1G1RB6E43CU100549	1G1RD6E40CU101295	1G1RD6E46CU101866	1G1RD6E4XCU102714
1G1RB6E43CU103497	1G1RD6E40CU101667	1G1RD6E47CU101651	1G1RD6E4XCU103233
1G1RB6E43CU105721	1G1RD6E40CU104357	1G1RD6E47CU101911	1G1RD6E4XCU104849
1G1RB6E44CU100818	1G1RD6E41CU109812	1G1RD6E47CU102086	1G1RH6E49CU125812

Please follow this diagnostic or repair process thoroughly and complete each step. If the condition exhibited is resolved without completing every step, the remaining steps do not need to be performed.



GENERAL MOTORS