



# Preliminary Information

## PIT5684 Intermittent No Start, Loss of Communication, Multiple DTCs

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Buick	Enclave	2018 - 2019	All	All	All	All
Cadillac	XT5	2017 - 2019	All	All	All	All
Chevrolet	Blazer	2019	All	All	All	All
Chevrolet	Traverse	2018 - 2019	All	All	All	All
GMC	Acadia	2017 - 2019	All	All	All	All

<b>Involved Region or Country</b>	<b>North America</b>
<b>Additional Options (RPO)</b>	
<b>Condition</b>	<b>A customer may complain that the vehicle will not start intermittently. A technician may find a loss of communication on the HSLAN and/or multiple DTCs.</b>
<b>Cause</b>	<b>Bent or damaged terminals at X203</b>

### **Correction:**

**Inspect connector X203 for bent or damaged terminals.  
Repair bent or damaged terminals as needed.**

### Warranty Information

For wiring repairs covered under warranty, please refer to latest version of bulletin [10-00-89-005](#) for warranty information on wire/connector repairs.

### Version History

Version	<b>1</b>
Modified	05/15/2019 - Created on

