



Preliminary Information

PIT5685 Removal / Deletion of Rear Fuel Tank

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 3500 Chassis Cab	2015 - 2019	All	All	All	All
GMC	Sierra 3500 Chassis Cab	2015 - 2019	All	All	All	All

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Involved Region or Country	North America
Additional Options (RPO)	N2N (Dual Fuel Tanks)
Condition	A Dealer or Upfitter may be looking for information on removing / deleting the rear fuel tank of a chassis cab truck with RPO N2N dual fuel tanks.
Cause	Information not readily available in Service Information (SI.)

Correction:

Reference the latest version of GM Upfitter Integration Bulletin 145. The information can be found at <http://www.gmupfitter.com/> under the "Technical Bulletin" Tab and then "Show all bulletins."

Version History

Version	1
Modified	05/17/2019 - Created on.

