

Bulletin No.: PIT5686 Published date: 05/17/2019

# **Preliminary Information**

## PIT5686 Adding or Installing a Rearview Camera

### <u>Models</u>

Brandt	Model:	Model Years:	VIN:		Engine	Transmissions
Brand:	Model.		from	to	Engine:	Transmissions:
Chevrolet	Silverado 4500HD, 5500HD, 6500HD	2019	All	All	All	All

The following diagnosis might be helpful if the vehicle exhibits the symptom(s) described in this PI.

Involved Region or Country	North America
Additional Options (RPO)	UVC
Condition	A Dealer or Upfitter may be looking for information on installing the factory provided rearview camera (RPO UVC.) Note: Camera, Extension Harness, and Mounting Bracket are shipped with the vehicle from the assembly plant.
Cause	Information not readily available in Service Information (SI.)

#### Correction:

Reference the latest version of GM Upfitter Integration Bulletin 150. The information can be found at http://www.gmupfitter.com/ under the "Technical Bulletin" Tab and then "Show all bulletins."

#### Version History

Version	1
Modified	05/17/2019 - Created on.



 $\ensuremath{\mathbb{C}}$  2019 General Motors. All Rights Reserved.