



Preliminary Information

PIP5653 Squeak chirp noise from front axle in 2wd

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	SU4
Condition	Squeak or chirp noise in 2wd gone in 4wd.
Cause	Under investigation by GM engineering

Some customers may comment on a squeak or chirp noise in 2wd that goes away in 4wd. Some people may also describe it as a metallic jingle, ringing, click or tick. Condition is easiest to duplicate in warmer ambient temperatures, after approximately 30 miles of driving and is barely audible. Technician may notice that the noise seems to be from the front left axle seal area. This information only applies to the SU4 axle.

At this time G.M. engineering is currently validating a repair. Please do not attempt any repairs at this time as current replacement parts could exhibit the same concern. There is no durability issue associated with this complaint and a repair should be available soon.

This PI will be updated when a repair is available.

Version History

Version	1
Modified	05/29/2019 - Created on.



GENERAL MOTORS