

# SS: 1034235 TBB Fault 6341/ 286 Fuel level out of Calibration

This Service Solution does not imply any special warranty coverage. Standard warranty guidelines and coverage apply. This Service Solution is provided to assist Dealers/Customers in resolving the issue of Fault 6341 or a Fuel level out of Calibration Fault.

## Applicable Vehicles

C2, HDX, EFX

## Symptoms

Check Engine light Fault 6341 or 286

## Solution:

Follow the Cummins Trouble shooting

After performing testing, possible running new over lays, Fault 286 also was reported

The Cluster will transmit a DM1 Fuel Level (SPN 96) Open Circuit (FMI 5) fault when Fuel Level is open.

Note: possible shavings or metal in the contactors? See attachment for the Sender New Fuel Sender to be installed

