

---

## **2014-2015 RLX Slow Air Leak from TPMS Area**

---

### **Background**

American Honda Motor Co., Inc. (AHM) is investigating certain 2014-2015 RLXs with a client complaint of slow air leak in the tires. To better understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

### **Qualifiers**

AHM is interested **ONLY** if the vehicle meets the following requirements:

1. Trim must be BASE.
2. Confirm that the slow air leak is coming from the TPMS area by placing the affected tire in a bucket of water & checking for bubbles.
3. No repair has been attempted for this issue.

### **Action Required**

If you have or know of such a vehicle, please call Technical Research & Support (TRS) Group at 800-880-1072. TRS will need to record certain vehicle information and provide you with further instructions.

Thank you.