

## LATEST VEHICLE CONCERN FIXES



Pop noise from audio output	17MY – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none"><li>– Popping sound or crackling noise from the audio system while in use.</li></ul> <p><u>Technical Description:</u></p> <ul style="list-style-type: none"><li>– Under investigation, may be IMC or AAM software.</li></ul> <p><u>Status:</u></p> <ul style="list-style-type: none"><li>– Primarily reported on Range Rover Velars but other models may be effected.</li><li>– Please raise a TA if a customer exhibits this issue and is not caused by a hardware failure of the speakers.</li></ul>	

