

Tech Tip T-TT-0542-19

May 03, 2019

Abnormal Noise f	rom Front	Over Bumps	and/or
During Turns			

USA

Suspension
Applicability

2019 Corolla

Front Suspension

APPLICABLE VEHICLES

2019	Corolla

CONDITION

Some 2019 model year Corolla vehicles may experience an abnormal noise from the front over bumps and/or during turns from the front lower arm bushing, both left and/or right sides.

RECOMMENDATIONS

This condition is currently under investigation. Confirm the condition by applying water to the bushing area. DO NOT USE SILICONE OR GREASE.

If the noise DOES change, please contact Technical Assistance (TAS) to submit details on any vehicles with the condition and to obtain further direction.

If the noise DOES NOT change, continue diagnosis using the applicable repair manual section.

If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available work day.

LINK REFERENCES

This Tech Tip does not contain any link references

Expires on