Knocking Noise Over Bumps With Cool Ambient Temps

USA

Service Category

Suspension

Front Suspension

2019 4Runner TRD PRO

APPLICABLE VEHICLES

2019 4Runner

CONDITION

Some 2019 model year 4Runner's equipped with the TRD PRO package and Fox shocks may experience a "knocking" noise over bumps with cool ambient temperatures, normally below 35 degrees Fahrenheit.

RECOMMENDATIONS

This condition is found to be a normal characteristic of the shock in cold temperatures. This is due to the nature of design on the internal shock structure. The characteristic is found to be result of the tuning required for the performance standards set for this shock package.

If there is a customer complaint for condition, please submit a field report.

LINK REFERENCES

This Tech Tip does not contain any link references