



May 2019

Technical Service Bulletin Notification TSB #19-026
Unit Serial Number:

Dear Valued Dealer:

Jayco has determined that certain Model Year 2019 Melbourne and Melbourne Prestige and Model Year 2020 Melbourne Prestige Class C motorhomes built on a Sprinter Chassis require a service appointment. Due to a signal variance, the dash may note an error message regarding the tail lights, when the lights are operating correctly. The Bulletin repair is to install a resistor assembly to correct the signal to the dash.

Our records indicate that the following unit is currently part of the inventory at your dealership and requires the Bulletin repair.

VIN

If you sold this affected vehicle, *please contact the current owner regarding this Service Bulletin and process the Warranty Registration for this customer.* All pertinent information regarding this Bulletin is on file under the Service and Parts Tab of our website. If you have questions regarding this Service Bulletin, please contact Jayco Motorized Customer Service at 800-517-9137.

We apologize for any inconvenience or concern this Bulletin may cause and want to assure you that Jayco is taking all the necessary steps to ensure our product quality meets your expectations.

Sincerely,
Jayco Motorized