



Service Product Journal

TITLE:

Not possible to left click ECUs in the network image for non-SPA cars

REF NO: US34753.1.0 en-US	ISSUING DEPARTMENT: Service Operations			REFERENCE BULLETINS:	
CATEGORY:	SUBCATEGORY:			CAR MARKET: United States and Canada	
Service Personnel: Read and initial	SERVICE MANAGER	SERVICE WRITER	WARRANTY ADMINISTRATOR	ISSUE DATE: 2019-05-07	STATUS DATE: 2019-05-09
				Page 1 of 3	

“Right first time in Time”

Attachment

File Name	File Size
Network_Image.PNG	0.0204 MB

Text

Background:

Only applies for Non-SPA vehicles which has the old network / topology image.

In the following locations in VIDA you will find a network map/image of the ECUs in the car.

Diagnostics -> Network

Diagnostics -> Fault Tracing

Diagnostics -> Vehicle Communication

Diagnostics -> Reference Information -> Fault Code Based

See attached screenshot for clarification.

Clicking any of the ECUs in this network image might not work due to a compatibility issues mostly found in Windows 10 but possibly also in Windows 7.

The problem is occurring when performing a regular left-click on the ECUs.



Temporary Solution:

Instead of using the left button on the mouse, use the right click button and the selection is possible.

Final Solution:

Investigation on-going

To view TJ attachment continue to next page. This TJ has one attachment.

