



Technical Journal

TITLE:

Ping noise from exhaust when cooling down

REF NO: TJ 34787.2.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2019-05-23	STATUS DATE: 2019-05-29
FUNC GROUP: 2520	FUNC DESC: Silencer and exhaust pipe	Page 1 of 2	

“Right first time in Time”

Attachment

File Name	File Size
Abnormal ping sound.m4a	1.3555 MB

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
224							2019-2099		-	201835-209952
224							2019-2099		-	201846-209952
225							2019-2099		-	201817-209952
227							2019-2099		-	201846-209952
234							2017-2099		-	201617-209952
235							2017-2099		-	201624-209952
236							2017-2099		-	201646-209952
246							2018-2099		-	201717-209952
256							2016-2099		-	201505-209952

CSC Customer Symptom Codes

Code	Description
XB	Exhaust system/Rattle/rumble

VST Operation Number



DTC Diagnostic Trouble Codes

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

Text

DESCRIPTION:

This journal is to collect information and case building.

If an abnormal ping sound from the silencer occurs when cooling down. (Listen in [attachment](#) after 8 seconds and 35 seconds)

Follow action under “service”

SERVICE:

Do not replace any part! A new silencer is planned 2020Q1.

Yes, please submit a Vehicle Report. Use concern area “Vehicle Report” and sub concern area “Support not needed”, use function group 2520.

Warranty claim info:

No warranty claim accepted for a job described in this TJ.

VEHICLE REPORT:

Yes, please submit a Vehicle Report for case building. Use concern area “Vehicle Report” and sub concern area “Support not needed”, use function group 2520.

This Technical Journal has an associated sound file.