

Attached is a drawing showing the tolerance allowed for the 6" X 4" aluminum hot product valve. Which is plus or minus 5 degree.

We have found that there were some plunger assemblies install out of tolerance.

The gasket could chaff or lodge in the valve housing set if not corrected.

Please inspect the stem plunger assembly and contact me for replacement parts if needed.

Please send me the address where I can send the mounting flange gasket so the discharge valve can be opened to inspect the plunger valve.

Any questions please call.



Thanks,
Ken Plumski
Tech Services Manager

Direct: 320-746-3434

Mobile: 320-761-7113

12810 County Road 17

Holdingford, MN 56340

kplumski@Entransinternational.com

