

SSM 48019 - 2017-2019 Continental - IPC Personalization Settings Reverting To Default Settings

Some 2017-2019 Continental vehicles may exhibit the user customizable personalization settings in the instrument panel cluster (IPC) reverting to their default settings. Do not attempt any repairs at this time. Engineering is investigating, monitor OASIS for updates.

APPLICABLE VEHICLES
2017 - 2019 CAR: CONTINENTAL