



Preliminary Information

PIP5629A 2019 Duramax Oil Life Monitor

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 2500/3500	2019	All	All	6.6 L5P	All
GMC	Sierra 2500/3500	2019	All	All	6.6 L5P	All

Involved Region or Country	North America
Condition	Some customers may have a concern that the engine oil life seems to be counting down too quickly.
Cause	The cause of the condition may be a software anomaly.

Correction:

Please refer to the latest version of service bulletin [19-NA-109](#).

Version History

Version	2
Modified	03/13/2019 - Created on 06/03/2019 - Updated to refer to service bulletin 19-NA-109.

