



Preliminary Information

PIT5682A Sunroof Sunshade Will Not Latch

Models

| Brand: | Model: | Model Years: | VIN: | | Engine: | Transmissions: |
|-----------|----------|--------------|------|-----|---------|----------------|
| | | | from | to | | |
| Buick | Enclave | 2018 - 2019 | All | All | All | All |
| Chevrolet | Traverse | 2018 - 2019 | All | All | All | All |
| GMC | Acadia | 2017 - 2019 | All | All | All | All |

| | |
|----------------------------|---|
| Involved Region or Country | North America |
| Condition | Some customers may comment that the front sunroof sunshade will not latch in the closed position. |
| Cause | The sunroof sunshade catch on the sunroof housing may be broken. |



Correction:

Replace the front sunroof sunshade catch with P/N 84691055.
Do NOT replace the Sunroof Housing for this condition.

Parts Information

| Description | Part Number | Quantity |
|-----------------------------|-------------|----------|
| RETAINER, SUN RF S/S FABRIC | 84691055 | 1 |

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

| Labor Operation | Description | Labor Time |
|-----------------|--------------------------|------------|
| 6041180 | Replace Sunshade Striker | 0.2 |

| Labor Operation | Description | Labor Time |
|--|-------------|------------|
| *This is a unique Labor Operation for Bulletin use only. | | |

Version History

| | |
|----------|---|
| Version | 1 |
| Modified | 05/13/2019 - Created on Modified to change the labor opp to 6041180 for 0.2. on 6/14/19 |



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.