



Bulletin No.: PIC6367
Published date: 06/26/2019

Preliminary Information

PIC6367 Insufficient Hood To Fender Clearance

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Trax	2018 - 2019	(VIN Position 1 = 3)	All	All	All

Involved Region or Country	North America
Condition	When opening the hood during a Pre-Delivery Inspection (PDI) the hood might make contact with the fender
Cause	Insufficient hood to fender clearance

Correction:

Check the hood to fender clearance. Adjust the hood as needed. Refer to the Hood Adjustment in SI.

Note: This PI may be converted into a bulletin when new information is available.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
1410052	Hood Adjustment	0.3

Version History

Version	1
Modified	06/26/2019 - Created on



GENERAL MOTORS

© 2019 General Motors. All Rights Reserved.