



# Preliminary Information

## PIT5694 Rear Heated Switch Indicators Inoperative

### Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Silverado 1500 (New Model)	2019	All	All	All	All
GMC	Sierra 1500 (New Model)	2019	All	All	All	All

Involved Region or Country	North America
Additional Options (RPO)	Rear Heated Seats (RPO KA6)
Condition	Some customers may comment that the rear heated seat switch indicators are inoperative or very dim. This concern is only noticed if the interior lamp dimmer switch is set to a very low setting. If the interior lamp dimmer switch is adjusted to a higher setting, the issue will no longer be present.
Cause	The cause of this concern is being investigated by engineering.

### Correction:

At this time, no repairs should be performed. If the interior lamp dimmer switch is adjusted to a higher setting, the concern(s) will go away. When a repair is available, this PI will be converted to a bulletin.

### Version History

Version	1
Modified	06/28/2019 - Created on



GENERAL MOTORS