

# WORK DESCRIPTION FOR FIELD MEASURE

**138 2018 303Code:** 19P5499601

**Version: 2.0**

## **Update telematics services N112/9 (HERMES) control unit software**

Model 167 with code 362

---

- i** • Ensure use of **XENTRY Diagnosis version** BD/DVD (**09/2018**) or higher.
- Before starting the work procedure, install the **current versions of all add-ons** in **XENTRY Diagnosis**.
- Make sure to follow the operation steps exactly as described in XENTRY Diagnosis.
- Use a battery charger to ensure sufficient power supply of the vehicle **on-board electrical system battery** (greater than 12.5 V).
- If XENTRY Diagnosis is already connected to the vehicle, start with **operation step 2**.
  - i** If two or more software updates or SCN codings are performed during one workshop visit, invoice operation items 02-4762 and 02-5058 **only once for each workshop order**.

### **Work procedure**

1. Connect XENTRY Diagnosis.
  2. Update telematics services N112/9 (HERMES) control unit software.
    - i** To do this, select menu item "Quick test view – N112/9 telematics services control unit (HERMES) - Adaptations – Control unit update – Update control unit software".
    - i** Then follow the user guidance in XENTRY Diagnosis.
  3. Disconnect XENTRY Diagnosis.
- 

### **Operation text and flat rate**

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-9334*	Update telematics services N112/9 (HERMES) control unit software (XENTRY Diagnosis connected)	0.1 h	54 996 01
02-4762**	Connect vehicle diagnosis system (XENTRY Diagnosis) and disconnect it	0.1 h	54 996 01
02-5058**	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1 h	54 996 01

---

\*\* Invoice operation item only once for each workshop order.

Mercedes-Benz  
Global Service & Parts