



Subject		Market
Abnormal Noise from Front - Loose Stabilizer Link Nut		USA
Service Category	Section	
Suspension	Front Suspension	
Applicability		
2019 ES350		

APPLICABLE VEHICLES

2019	ES350
------	-------

CONDITION

Some 2019 model year ES350 vehicles may experience a clunking/abnormal noise from the front of the vehicle when driving. Upon further inspection, the noise is due to a loose stabilizer link nut.

RECOMMENDATIONS

DO NOT REPAIR OR TIGHTEN.
This condition is currently under investigation. Please contact Technical Assistance (TAS) to submit details on any vehicles identified matching the condition and to obtain further direction.

If it is a weekend or holiday, continue with diagnosis and repair. Please save all parts and/or details and contact TAS on the next available work day.

LINK REFERENCES

This Tech Tip does not contain any link references