

# LATEST VEHICLE CONCERN FIXES



## Telematics Control Unit Software Download Performance

18MY – 19MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport

### Customer Voice:

- TCU\_3 programming failures

### Technical Description:

- TCU\_3 software download incomplete due to software iteration step.

### Status:

- This software download failure is only present on a LG TCU\_3 equipped on 18MY & 19MY vehicles.
- Please follow TOPIx Workshop Manual Guided Flow for TCU diagnosis.
  - 415-01
- Current TCU programming is very similar to old IMC software download (Phase 2.5 → Phase 4 → current sw)
  - Supplier is working on providing TCU delta software to skip the sw that may fail during download.
  - If download failure will be evident and can not be skipped Pathfinder will state to replace the TCU.

