


LATEST VEHICLE CONCERN FIXES



Pop noise from audio output	17MY – 20MY E-PACE, F-PACE, I-PACE, F-TYPE, XE, XF, XJ, Range Rover, RR Sport, RR Velar, RR Evoque, Discovery, Discovery Sport with InControl Touch Pro Audio System
<p><u>Customer Voice:</u></p> <ul style="list-style-type: none">– Popping sound or crackling noise from the audio system while in use. <p><u>Technical Description:</u></p> <ul style="list-style-type: none">– Under investigation, may be IMC or AAM software. <p><u>Status:</u></p> <ul style="list-style-type: none">– Primarily reported on Range Rover Velars but other models may be effected.– Please raise a TA if a customer exhibits this issue and is not caused by a hardware failure of the speakers.	 A close-up photograph of two circular speakers mounted in a car's interior. The speakers have a silver mesh grille and are set into a dark, possibly leather or plastic, surface. The lighting is dramatic, highlighting the texture of the mesh and the surrounding material.

