

Special Bulletin

SP19-26A

Date	Expiration	Release	Page
07.2019	07.2021	2	1(2)

Revision A OBD19 Vehicles added to involved vehicles box 07-08-2019

GLI ENGINE EMS UPDATE

Prevost vehicles

DESCRIPTION

On the vehicles affected by this bulletin, an update to the engine EMS software must be carried out by qualified technicians. Contact your Service Manager to schedule an appointment and have the update performed.


MODEL YEAR(S) AND VEHICLES INVOLVED

NOTICE TO SERVICE CENTERS	
<i>Verify vehicle eligibility by checking warranty bulletin status with SAP or via ONLINE WARRANTY SYSTEM available on Service / Warranty tab of Prevost website.</i>	
Model	VIN
X3-45 coaches	from 2PCG33491J <u>C736245</u> up to 2PCG33493K <u>C736488</u> incl.
Model Year : 2018 - 2019	from 4RKG33494J <u>9737448</u> up to 4RKG33495K <u>9737640</u> incl.
This bulletin does not necessarily apply to all the above-mentioned vehicles, some vehicles may have been modified before delivery.	

MATERIAL NEEDED

No material required for this bulletin.

PROCEDURE

 DANGER
<p>Park vehicle safely, apply parking brake, stop engine. Prior to working on the vehicle, set the ignition switch to the OFF position and trip the main circuit breakers equipped with a trip button. On Commuter type vehicles, set the battery master switch (master cut-out) to the OFF position.</p> <p>Lock out & Tag out (LOTO) must be performed during set-up, maintenance or repair activities. Refer to your local procedure for detailed information regarding the control of hazardous energy.</p>

Date	Expiration	Release	Page
07.2019	07.2021	2	2(2)

1. Connect Premium Tech Tool (PTT) to the vehicle diagnostic connector (OBD). Connect PC to a functional LAN or Wi-Fi connection and power source.
2. Turn the vehicle ignition switch to the ON position.
3. Using PTT, update EMS software.
 - In the "Program" tab, select "Program Electronic Control Unit" then "Engine Control Module (EMS)".
 - Follow the instructions until update completion.

ESTIMATED TIME

The time required to perform this special bulletin is approximately half an hour (0.5).

OTHER

VBC Bulletin	N/A
Fail Code	6.27-2
Defect Code	49
Syst. Cond	B
Causal Part	3092091

Access all our Service Bulletins on
<http://techpub.prevestcar.com/en/>
or scan the QR-Code with your smart phone.



Prevast engages in a continuous program of testing and evaluating to provide the best possible product. Prevast, however, is not committed to, or liable for updating existing products.