

NUMBER: 14-001-19

GROUP: 14 - Fuel System

DATE: May 29, 2019

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

SUBJECT:

P018C - Fuel Pressure Sensor Circuit Low

OVERVIEW:

This bulletin involves replacing the fuel pressure sensor due to a P018C Diagnostic Trouble Code (DTC).

MODELS:

2019 (VM) RAM ProMaster City

NOTE: This bulletin applies to vehicles within the following markets/countries: NAFTA.

NOTE: This bulletin applies to vehicles built on or after August 03, 2018 (MDH 0803XX) and on or before August 13, 2018 (MDH 0813XX) equipped with a 2.4L I4 Multiair Engine (Sales Code ED6).

SYMPTOM/CONDITION:

Customers may experience a Malfunction Indicator Lamp (MIL) illumination. Upon further investigation the technician may find that the following Diagnostic Trouble Code (DTC) has been set:

P018C - Fuel Pressure Sensor Circuit Low.

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DelaerCONNECT/Service Library, verify all related systems are functioning as designed. If DTCs or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes the symptom/condition listed above or if the technician finds the DTC, perform the Repair Procedure.

PARTS REQUIRED:

Qty.	Part No.	Description
1	68338428AA	Fuel Pressure Sensor (line w/ sensor)

REPAIR PROCEDURE:

1. Replace the fuel pressure sensor/fuel line. Refer to the detailed service procedures available in DealerCONNECT/Service Library under: Service Info 14 - Fuel System / Fuel Delivery, Gas / Sensor. Fuel Rail Pressure / Removal and Installation.

14-001-19 -2-

NOTE: The fuel pressure sensor and fuel line come as one piece, they do not come separately.

POLICY:

Reimbursable within the provisions of the warranty.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
14-70-10-97	Sensor, Fuel pressure (with line) - Replace (2 - Skilled)	1 - Engine Repair and Performance	0.4 Hrs.

FAILURE CODE:

ZZ	Service Action