

WORK DESCRIPTION FOR FIELD MEASURE

Code: 19P4991003

Version: 2.0

Replace left and right tailpipe trim

Model 290

i Code P90 corresponds to AMG PACKAGE EXTERIOR.

Work procedure

1. Remove rear bumper.
i For basic data, see AR88.20-P-2200FRX.
2. Replace left and right tailpipe trim.
i For basic data, see AR88.20-P-2100FRX.
3. Assemble in reverse order.

Parts

Quantity	Designation	Part number
As required (1)*	Left tailpipe trim	A 290 490 15 01
As required (1)*	Right tailpipe trim	A 290 490 16 01
As required (1)*	Left tailpipe trim (black chrome; P60)	A 290 490 17 01
As required (1)*	Right exhaust tip (black chrome; P60)	A 290 490 18 01

* The replacement parts must be determined according to the equipment variant for the vehicle identification number via the parts job in the Xentry Portal.

Operation text and flat rate

Operation no.	Operation text	Flat rate	Accounting no./ damage code
02-2971	Replace left and right tailpipe trim Comprises: removal and later reassembly of rear underbody paneling; removal and later reassembly of rear bumper; adjustment of reversing camera; adjustment of 360-degree camera	1.4 h	49 910 03
02-4762*	Connect/disconnect vehicle diagnosis system (XENTRY Diagnosis)	0.1 h	49 910 03
02-5058*	Connect/disconnect starter battery charger (with XENTRY Diagnosis connected)	0.1 h	49 910 03

* Operation item may be invoiced only once for each workshop order!