



# Latest Vehicle Concern Fixes



| Engine Cooling Fan Pulley   | 2019 RR Sport with AJ20P6  |
|---|--|
| <p><b><u>Customer Voice:</u></b></p> <ul style="list-style-type: none"><li>• There is a noise from the engine compartment.</li></ul> <p><b><u>Technical Description:</u></b></p> <ul style="list-style-type: none"><li>• The engine fan pulley/bracket has come adrift.</li></ul> <p><b><u>Status:</u></b></p> <ul style="list-style-type: none"><li>• Make repairs necessary based on the extent of the damage that has occurred.</li><li>• Raise an EPQR as soon as the vehicle arrives including pictures showing the condition of the FEAD system.</li><li>• An ESST shipment should leave the warehouse this week which includes the P6 specific tools outlined for this repair.</li></ul> |   |

